

<b>A/C</b>	<b>Type</b>	<b>MN Wing Aircraft Discrepancies</b>
N369CP	172S	50 hour inspection due
N50935	172P	DF RADIO INOP. IF NO INTENTION TO REPAIR, KEEP THIS DISCREPANCY OPEN
N643CP	182T	Cosmetic plug on throttle knob missing.
N643CP	182T	Defrost knob missing. Cmx ordered part.
N828CP	182T	#1 cylinder r/h baffle assembly is broken. Temporary repair done at last Inspection.
N828CP	182T	Cyl head temp gauge erratic/inop
N837CP	172S	100 hour annual inspection due
N96579	172P	GTN650 message saying SD card data corrupted
N96579	172P	In straight and level flight, turn coordinator reports a slight right turn
N9834L	172P	Requesting a GNS 400 upgrade and replacement of #1, #2 nav/comm, KX155
N9834L	172P	Comm 1 inop. Comm 2 works.
N98424	172P	Original seat covers are worn out.
N98824	172P	100 hour annual inspection due
N98824	172P	DME INOP. (avionics upgrade pending)
N9912L	172P	Need 100 hour inspection