

A/C	Type	MN Wing Aircraft Discrepancies
N439CP	182T	BECKER NOT CAPTURING DESPITE STRONG ELT SIGNAL
N439CP	182T	Engine TBO/due overhaul @ 2000.0
N50935	172P	Request NHQ to supply database adaptor for gps G400.
N50935	172P	GPS INOP
N50935	172P	Both landing & taxi lights inop. Lights are located in lower front cowl and will be replaced
N50935	172P	Requesting NHQ to supply GNS 400W installation package & CAP/FM upgrade.
N50935	172P	Per NHQ approval 9/25, inop DF system, inop ADF system and DME to be removed
N5154D	172N	50 hour inspection due
N643CP	182T	Voltage erratic on main buss
N695CP	172S	50 hour inspection due
N828CP	182T	#1 cylinder r/h baffle assembly is broken. Temporary repair done at last Annul Inspection.
N97465	172P	Requesting NHQ provide database adapter/loader for Garmin 400.
N9834L	172P	Request NHQ to provide gps database card adaptor for G400.
N9834L	172P	Need USB aviation data card programmer for the G400. PN: 010-10579-20
N9834L	172P	Requesting NHQ to supply KI-209-A Nav indicator or equivalent for GNS 400W system
N98424	172P	Compass deviation. DG precesses. G650 auto dimming not working.
N98424	172P	Original seat covers are worn out.
N98824	172P	DME INOP. (avionics upgrade pending)
N9912L	172P	No mag drop on runup. Monitor this.
N9912L	172P	Tanis heater inop