

<b>A/C</b>	<b>Type</b>	<b>MN Wing Aircraft Discrepancies</b>
N369CP	172S	50 hour due 1133.1, 100 hour due 1134.0
N50935	172P	Corrosion control due September.
N643CP	182T	50 hour due 950.9, 100 hour due 955.0
N837CP	172S	Reading light, 12v charging port, Comm 2, upper vent, Left mag drop
N853CP	182T	Back left seat tilts back.
N98175	172P	100 hour/annual due 5622.2
N98424	172P	Right ptt intermittent.
N9912L	172P	100 hour/annual due 5506.9
N9912L	172P	2-3 in long crack in left elevator tip fairing.